CReddy




TOTAL O2 Sensor Adapter 1

This adapter is used to cut the 02 sensor feedback signal. e-manage jumper settings will need to be set to VTEC control. Some vehicle may get a check engine light or run in safe mode when using this adapter.

《How to Connect》

- 1. Cut the 02 sensor wire and connect the white wire to the 02 sensor wire (sensor side), and the green wire to the 02 sensor wire (ECU side).
- 2. Connect the Black wire to a good ground.
- 3. Connect the Yellow wire to the e-manage VTEC Output wire (Yellow).



GReddy



02センサー アダプタ1

02センサー信号線を設定回転数以上で切り離すアダプタです。

e-manageのジャンパー設定(VTEC車両)が必要です。

車両によってはエンジンチェックランプが点灯したり、フューエルセーフモードになる可能性があります。

《配線方法》

- 1. 02センサー信号線をカットし、アダプタの白線をセンサー側に、緑線をECU側に 配線します。
- 2. アダプタの黒線をアースに配線します。
- 3. アダプタの黄線をe-manageの黄線(VTEC出力)に配線します。

