GReddy




MULTI SWITCHING SYSTEM Adapter

This adapter is used to monitor the MULTI SWITCING SYSTEM (NOS) activation signal.

Must use support tool 1.20 and e-manage 1.40 and above. $\langle\!\!\langle$ How to use $\rangle\!\!\rangle$

- 1. Connect the Adapter Yellow wire to the desired signal MSS signal wire.
- 2. The yellow connector on the adapter will plug into the e-manage "BOOST" port or e-manage Ultimate "OPTION" port.



EReddy



MULTI SWITCHING SYSTEM 認識アダプタ

MULTI SWITCING SYSTEM (NOS等)の駆動信号をe-manageに認識させる為のアダプタです。

Support Tool ver1.20, e-manage ver1.40以上でご使用下さい。

《配線方法》

- 1. 認識させたいMSSの駆動信号ハーネスに黄線を配線します。
- 2.アダプタから出ているコネクタをe-manageのプレッシャーセンサー接続 コネクタに接続します。

